



Vehicle History Report #: 64756559
Report Date: October 1, 2025 | 2:59 p.m. EDT
Report Status: Complete

2014 CHEVROLET EXPRESS G3500 LT

Van passenger | 8 Cylinders | Flexible
1GAZG1FG5E1205787
Country of Assembly: United States
Last Reported Odometer: 259,761 KM



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



19 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of October 01, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2015 Oct 6	Ontario, Canada	
	Claim: Collision	\$0.00
	Claim: Collision	\$0.00



Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.
We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2014 Jul 31		City Buick Chevrolet Cadillac GMC North York, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed
2020 Feb 24	90,365 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Air filter checked Air filter replaced Oil and filter changed
2020 May 1	99,078 KM	Great Canadian Oil Change Markham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2020 Aug 28	110,567 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2021 Jun 1	137,948 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Air filter checked Air filter replaced Fluids checked Oil and filter changed
2021 Oct 6	150,770 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed
2022 Jan 26	161,322 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked

1GAZG1FG5E1205787

	ODOMETER	SOURCE	DETAILS
			<ul style="list-style-type: none"> Oil and filter changed
2022 May 6	172,311 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Air filter checked Air filter replaced Fluids checked Oil and filter changed
2022 Jul 8	110,633 KM	Tsk Auto Repair Brampton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> POTENTIAL ODOMETER ROLLBACK
2022 Aug 25	112,537 KM	Tsk Auto Repair Brampton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Front wheel bearing(s)/hub(s) replaced Ignition system checked Starter replaced Transmission fluid flushed Transmission replaced
2022 Sep 26	113,726 KM	Tsk Auto Repair Brampton, Ontario, Canada	Vehicle serviced
2022 Oct 13		Jiffy Lube #2876 Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed
2023 Apr 17	206,836 KM	Oil Changers - Kingston Rd Scarborough, Ontario, Canada	Vehicle serviced
2023 Sep 11	218,261 KM	Dennis Auto Repair Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Fuel injection system flushed/serviced Ignition coil(s) replaced Spark plug wires replaced Spark plug(s) replaced
2023 Sep 27	220,128 KM	Dennis Auto Repair Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Antifreeze/coolant checked Antifreeze/coolant flushed/changed Cooling system checked Thermostat replaced Water pump gasket replaced Water pump replaced
2023 Oct 25	222,448 KM	Dennis Auto Repair Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Front brake pads replaced Front brake rotor(s) replaced
2024 Mar 28	241,797 KM	Dennis Auto Repair Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> ABS system checked
2024 May 16	247,054 KM	Dennis Auto Repair Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Front wheel bearing(s)/hub(s) replaced Rear door latch replaced
2024 Aug 14	259,761 KM	Dennis Auto Repair Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Alignment performed Ignition coil(s) replaced Oxygen sensor replaced Shifter cables adjusted Spark plug wires replaced Tune-up performed



Open Recalls

Recall #: N172086770 | Driver Side Window Switch Inoperative Recall Date: 2018 May 03

Recall Description

General Motors has decided that a defect which relates to motor vehicle safety exists in 2014 – 2017 Chevrolet Express and GMC Savana vehicles (built through 6/21/16 and 6/17/16 respectively) equipped with power windows. Under certain conditions, liquid can enter the power window switches in these vehicles and cause corrosion, leading to high electrical resistance. High electrical resistance can cause the switch to heat up, smoke or melt, increasing the risk of fire and injury. Occupants may notice that the power window is malfunctioning or inoperative. Smoke or an odor from smoke or melting may also come from the door panel.

Remedy

Replace driver side door window switch.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit [GM's website](https://my.gm.ca/gm/en/recalls). (https://my.gm.ca/gm/en/recalls)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Jul 31		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as blue
2014 Jul 31		City Buick Chevrolet Cadillac GMC North York, Ontario, Canada	Service Record	Vehicle serviced
2015 Oct 6		Insurance Records Canada		
2015 Oct 6		Ontario, Canada	Collision	
2018 May 3		CHEVROLET	Recall	Manufacturer Recall Issued Recall # N172086770
2019 Jan 9	69,469 KM	Auto Auction Toronto, Ontario, Canada	Auction Announcement	AUCTION ANNOUNCED AS PREVIOUS DAILY RENTAL
2019 Aug 7		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Commercial Vehicle colour noted as blue
2020 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial

1GAZG1FG5E1205787

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2020 Feb 24	90,365 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Service Record	Vehicle serviced
2020 May 1	99,078 KM	Great Canadian Oil Change Markham, Ontario, Canada	Service Record	Vehicle serviced
2020 Aug 28	110,567 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Service Record	Vehicle serviced
2021 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as blue
2021 Jun 1	137,948 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Service Record	Vehicle serviced
2021 Oct 6	150,770 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Service Record	Vehicle serviced
2022 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as blue
2022 Jan 26	161,322 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Service Record	Vehicle serviced
2022 May 6	172,311 KM	Great Canadian Oil Change Brampton, Ontario, Canada	Service Record	Vehicle serviced
2022 Jul 8	110,633 KM	Tsk Auto Repair Brampton, Ontario, Canada	Service Record	Vehicle serviced
2022 Aug 25	112,537 KM	Tsk Auto Repair Brampton, Ontario, Canada	Service Record	Vehicle serviced
2022 Sep 26	113,726 KM	Tsk Auto Repair Brampton, Ontario, Canada	Service Record	Vehicle serviced
2022 Oct 13		Jiffy Lube #2876 Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2023 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as blue
2023 Apr 17	206,836 KM	Oil Changers - Kingston Rd Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2023 Sep 11	218,261 KM	Dennis Auto Repair Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2023 Sep 27	220,128 KM	Dennis Auto Repair Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2023 Oct 25	222,448 KM	Dennis Auto Repair Mississauga, Ontario, Canada	Service Record	Vehicle serviced

1GAZG1FG5E1205787

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2024 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2024 Mar 28	241,797 KM	Dennis Auto Repair Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2024 May 16	247,054 KM	Dennis Auto Repair Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2024 Aug 14	259,761 KM	Dennis Auto Repair Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2025 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.

